



Inspection Report

Inspection Date: 2025/12/11

Excavators

General Information	
Maker	KUBOTA
Model Number	U-40-6E
Year	2017
Hour (h)	4674
Meter	Working
Serial Number	30665

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings
- Arm Crane	

Upper Structure			
		Cylinder	
		Oil Leak	Scratch/Rust
Boom	Left	No	No
	Right	No	No
Arm		No	No
Bucket		No	No
Bucket Size (mm)		600	

Note for External Appearance	
- The body has scratches, rust, and dents	- The body is dirty
- No VIN plate	



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	350	350
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure	

Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component	

Note for Engine	

Admin No. 3000079578

*This report is only for your reference. We are not responsible for the actual condition of checked item.