

ZX225USR-3 Hydraulic Shovel

2019/12/26

BASIC INFORMATION

Inspection Date		Model	ZX225USR-3	Serial No.	208237
Date of Manufacture		Hourmeter	6951 HR	Condition of Hourmeter	HR is normal
Hourmeter (Estimated)		Engine No.		Job Status	Rental
Accident History		Cabin/Canopy	Cabin	Cabin Type	Standard
Front Attachment	Standard	Super long length(m)		Type of Shoe	Grouser
Width of Track Shoe	800	Bucket/Attachment	Standard BK	Stamp	
Others	EPA, Air Conditioner, ML Crane, Multi Lever				

OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Swing	Normal
Wear: Swing Bearing	Moderate/Within Service Limit	Traveling	Normal	Front Attachment	Normal
Pump Device	Normal				

UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	No	Wear: Track Link Extension (Right)	Excessive	Wear: Track Link Extension (Left)	Excessive
Wear: Track Link Tread(Right)	Moderate/Within Service Limit	Wear: Track Link Tread(Left)	Moderate/Within Service Limit	Wear: Track Link Pins (Right)	Moderate/Within Service Limit
Wear: Track Link Pins (Left)	Moderate/Within Service Limit	Wear: Track Shoe/Rubber Shoe	Moderate/Within Service Limit	Bent/Broken/Missing: Track Shoe	1~4 Pieces
Wear: Rubber Pad		Broken/Missing: Rubber Pad		Missing: Rubber Pad	
Broken/Crack: Rubber Shoe(Right)		Broken/Crack: Rubber Shoe(Left)		Missing: Rubber Shoe Core	
Wear: Upper Rollers	Moderate/Within Service Limit	Wear: Lower Rollers	Moderate/Within Service Limit	Oil Leak: Rollers	None
Broken/Missing: Rollers	None	Wear: Front Idler (Right)	Excessive/Need Replacement	Wear: Front Idler(Left)	Moderate/Within Service Limit
Wear: Sprocket(Right)	Moderate/Within Service Limit	Wear: Sprocket(Left)	Moderate/Within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

FRONT & PINS

Boom	Normal	Arm	Normal	Wear: Boom Foot Pin	Moderate/Within Service Limit
Wear: Boom/Arm Joint Pin	Moderate/Within Service Limit	Wear: Arm Tip Pin	Moderate/Within Service Limit	Wear: Other Pins	Moderate/Within Service Limit
Wear/Deformation: Bucket	Wear: Moderate/Within Service Limit, Deformation: Moderate	Wear/Deformation: Blade			

OIL/WATER/AIR LEAK

Oil Leak: Front Pipes	No	Oil Leak: Boom Cylinder (Right)	No	Oil Leak: Boom Cylinder (Left)	No
Oil Leak: Arm Cylinder (Right)	No	Oil Leak: Arm Cylinder (Left)		Oil Leak: Bucket Cylinder (Right)	No
Oil Leak: Bucket Cylinder (Left)		Oil Leak: Offset Cylinder		Oil Leak: Blade Cylinder	
Oil Leak: Engine	No	Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No
Oil Leak: Pilot Valve	Moderate Oozing	Oil Leak: Center Joint	Slight Film	Oil Leak: Swing Device	No
Oil Leak: Pump Device	No				

APPEARANCE

Engine Cover	Deformed/Dent, Cracked, Rusted/Corroded カバー変形有り、ロックしない。	Side Covers	Deformed/Dent, Rusted/Corroded	Under Covers	Deformed/Dent, Rusted/Corroded
Counter Weight	Scratched, Rusted/Corroded	Main frame	Rusted/Corroded	D Frame	Deformed/Dent, Rusted/Corroded
Track Frame	Rusted/Corroded	Cabin	Deformed/Dent, Rusted/Corroded	Door	Good Condition

INTERIOR

Cabin Interior	Good Condition	Seat	Torn	Console	Broken, Faded
Air conditioner	Good Condition	Freon gas inspection	Good Condition		

OVERALL RATING

Appearance Evaluation	Repainted	Rust/Corrosion	Moderate	Overall Rating	Fair
Special Notes	MLクレーン、バケットロックしない。				