



# Inspection Report

Inspection Date: 2019/02/19

## Excavators

### General Information

|                      |            |              |         |
|----------------------|------------|--------------|---------|
| <b>Maker</b>         | SUMITOMO   |              |         |
| <b>Model Number</b>  | SH75XU-3   |              |         |
| <b>Year</b>          | 2003       |              |         |
| <b>Hour (h)</b>      | 6991       | <b>Meter</b> | Working |
| <b>Serial Number</b> | 075X3-2047 |              |         |

### Options

|              |                   |
|--------------|-------------------|
| - CAB        |                   |
| - Multilever | - Air conditioner |
| - Blade      |                   |
| - Arm Crane  |                   |

### Upper Structure

|                  |       | Cylinder |              | Play  |
|------------------|-------|----------|--------------|-------|
|                  |       | Oil Leak | Scratch/Rust |       |
| Boom             | Left  | No       | No           | Small |
|                  | Right | N/A      | N/A          |       |
| Arm              |       | No       | No           | No    |
| Bucket           |       | No       | No           | Small |
| Bucket Size (mm) | 720   |          |              |       |

### Note for External Appearance



### Undercarriage

| <b>Shoe Type</b>       | Steel shoes with rubber pads |       |
|------------------------|------------------------------|-------|
| <b>Swing Circle</b>    | No oil leak                  |       |
|                        | Left                         | Right |
| <b>Shoe Width (mm)</b> | 450                          | 450   |
| <b>Idler</b>           | OK                           | NG    |
| <b>Sprocket</b>        | OK                           | OK    |
| <b>Pin Bush</b>        | OK                           | OK    |
| <b>Upper Roller</b>    | OK                           | OK    |
| <b>Track Roller</b>    | OK                           | OK    |
| <b>Shoe Link</b>       | OK                           | OK    |

### Note for Upper Structure

The blade has some dents


### Note for Undercarriage

Oil oozing from the reduction drive of the right travel motor

### Engine

|                         |               |
|-------------------------|---------------|
| <b>Model</b>            | 4TNE98-SH     |
| <b>Serial Number</b>    | 26373         |
| <b>Engine Oil Leak</b>  | No oil leak   |
| <b>Engine Oil Gauge</b> | Unchecked     |
| <b>Radiator</b>         | Normal        |
| <b>Exhaust Color</b>    | Normal        |
| <b>Blow-by</b>          | No            |
| <b>Engine Sound</b>     | OK            |
| <b>Hydraulic Pump</b>   | No oil leak   |
| <b>Water Pump</b>       | No water leak |
| <b>Oil Cooler</b>       | No oil leak   |
| <b>Motor</b>            | No oil leak   |
| <b>Multi Lever</b>      | No oil leak   |

### Note for Operating Component



### Note for Engine



Admin No. 2019020338