



Inspection Report

Inspection Date: 2019/08/23

Generator

General Information

Maker	DENYO
Model Number	DAW-300SS
Year	2006
Hour (h)	887
Serial Number	3787407

Note for External Appearance

- The surface is partly deformed
- The side panels have some scratches

Engine

Model	D722-KB
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	Unchecked
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Admin. No. 2019080103

*This report is only for your reference. We are not responsible for the actual condition of checked item.