



Inspection Report

Inspection Date:

#N/A

General Information

Maker	ISUZU
Model Number	SKG-NKR85YN
Year	2014
Hour (h)	3077
Serial Number	国 [01] 185175

Note for External Appearance

- Model: AICHI TZ12A 749861 2014yr
- Mileage: 52,539km
- Vehicle with stamped authority: Former KR85Y-7004662
- Maximum loading capacity of work platform: 1,000kg
- Maximum ground height: 12m
- The frame is rusty and corroded

Engine

Model	4JJ1
Serial Number	1J4876
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- Automatic car

Note for Engine

Other Information

- Temporary deregistration certificate is included

Admin. No. 3000080875

*This report is only for your reference. We are not responsible for the actual condition of checked item.