



Inspection Report

Inspection Date: 2018/04/12

Generator

General Information

Maker	DENYO
Model Number	DCA-90SPH
Year	2002
Hour (h)	5337
Serial Number	3710808

Note for External Appearance

Engine

Model	H07D-C
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Engine oil quantity and condition of the injection pump are unchecked

Admin. No. 2018040357

*This report is only for your reference. We are not responsible for the actual condition of checked item.