



Inspection Report

Inspection Date: 2024/03/23

Excavators

General Information

Maker	KOMATSU		
Model Number	PC228US-11		
Year	2019		
Hour (h)	7841	Meter	Working
Serial Number	KMTPC276AKC006933		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	1170			

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The upper structure is dirty



Note for Undercarriage

- The undercarriage is dirty



Engine


Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

- The engine room is dirty



Admin No. 3000057023