



Inspection Report


Inspection Date: 2018/05/12

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK225SR		
Year	2013		
Hour (h)	3724	Meter	Working
Serial Number	YB06-03928		


Options	
- CAB	- Speed changer
	- Air conditioner
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		1040		


Note for External Appearance
Repainted


Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
2 sides of the arm have are reinforced


Note for Undercarriage
Spin turns are not checked


Engine	
Model	J05E-TA
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat has some holes


Note for Engine


Admin No. 2018020322