



Inspection Report


Inspection Date: 2018/08/07

Excavators


General Information			
Maker	CAT		
Model Number	313BSR		
Year	2000		
Hour (h)	8322	Meter	Working
Serial Number	9PR01283		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		820		


Note for External Appearance


Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The blade is partly worn and has some dents


Note for Undercarriage
<ul style="list-style-type: none"> - The rubber pads have deteriorated over time and are partly worn - Traveling motion is unchecked because there was not enough space for inspection


Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	-

Note for Operating Component
<ul style="list-style-type: none"> - The seat is partly torn - Some parts around the safety lever are damaged - No radio unit


Note for Engine


Admin No. 2018080023