



# Inspection Report

Inspection Date: 2023/09/13

## Excavators

### General Information

Maker	KOMATSU		
Model Number	PC200-8N1		
Year	2013		
Hour (h)	7472	Meter	Working
Serial Number	KMTPC197K02357967		

### Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		1030		

### Note for External Appearance



### Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	800	800
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure

- No bucket side cutters



### Note for Undercarriage

- The right shoe plates is damaged



### Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

### Note for Operating Component

- The seat is torn
- The air conditioner is broken



### Note for Engine

- The battery is flat; it starts with booster cables



Admin No. 3000051537

\*This report is only for your reference. We are not responsible for the actual condition of checked item.