



Inspection Report


Inspection Date: 2019/01/11

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO30-5B		
Year	2011		
Hour (h)	3483	Meter	Working
Serial Number	54566B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		475		


Note for External Appearance


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
Quick hitch 

Note for Undercarriage
Oil oozing from the right travel motor 

Engine	
Model	3TNV82A-N
Serial Number	86733
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn 

Note for Engine


Admin No. 2019010049