



Inspection Report

Inspection Date: 6/28/2016

Excavator

General Information

Maker	SUMITOMO
Model Number	SH75X-3
Year	2007
Hour (h)	3267
Serial Number	07 [REDACTED]

Note for External Appearance

- Repainted
- Dented cover



Upper Structure

Boom Cylinder (Left)	No oil leak
Boom Cylinder (Right)	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	720
Swing	Backlash and play

Note for Upper Structure

- The bucket and arm have plays
- Equipped with arm crane and pipings
- The boom gradually drops by itself



Note for Undercarriage



Undercarriage

Swivel Joint	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Operating Component

- Multi lever
- Air conditioner not working



Engine

Model	4TNE98-SH
Serial Number	35122
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	Oil oozing
Motor	No oil leak
Multi Lever	No oil leak

Note for Engine

- Oil oozing from the engine head and control valve
- Not enough hydraulic oil

