



Inspection Report

Inspection Date: 2018/09/29


Excavators

General Information			
Maker	SUMITOMO		
Model Number	SH225X-3		
Year	2006		
Hour (h)	5308	Meter	Working
Serial Number	225X3-5187		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	No	No	
Arm		No	No	No
Bucket		No	Yes	Small
Bucket Size (mm)		1020		

Note for External Appearance
Repainted




Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- Complete washing is not applicable (bucket)
- The boom has some dents




Note for Undercarriage
Oil oozing from the reduction drive of the left travel motor




Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Black/Gray
Exhaust Color	Black/Gray
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine
The engine produces black exhaust smoke under pressure



Admin No. 2018090591