



Inspection Report


Inspection Date: 2018/07/20

Excavators


General Information			
Maker	KOMATSU		
Model Number	PC128US-2		
Year	2005		
Hour (h)	7395	Meter	Working
Serial Number	6369		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		Oil oozing	Yes	Small
Bucket Size (mm)		830		


Note for External Appearance



Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	NG	OK
Track Roller	NG	OK
Shoe Link	OK	OK

Note for Upper Structure
The bucket teeth are worn


Note for Undercarriage


Engine	
Model	S4D102E-1-A
Serial Number	26271299
Engine Oil Leak	No oil leak
Engine Oil Gauge	Rust/Oil
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for Operating Component
The seat is partly torn


Note for Engine
Unusual sound from the air conditioner compressor (clutch)


Admin No. 2018070742