



# Inspection Report

Inspection Date: 2022/09/01

## Excavators

### General Information

<b>Maker</b>	KOMATSU		
<b>Model Number</b>	PC128US-8		
<b>Year</b>	2012		
<b>Hour (h)</b>	5357	<b>Meter</b>	Working
<b>Serial Number</b>	KMTPC189A01029575		

### Options

- |              |                   |
|--------------|-------------------|
| - CAB        | - Speed changer   |
| - Multilever | - Air conditioner |
| - Blade      |                   |
| - Arm Crane  |                   |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)	800			

### Note for External Appearance



### Undercarriage

<b>Shoe Type</b>	Steel shoes with rubber pads	
<b>Swing Circle</b>	Oil oozing	
	<b>Left</b>	<b>Right</b>
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure



### Note for Undercarriage

- Some pads are worn
- With 4-digit security code number



### Engine

<b>Model</b>	SAA4D95LE-5
<b>Serial Number</b>	535522
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 3000042466