



# Inspection Report

Inspection Date: 2018/03/13

## Wheel Loader

### General Information

<b>Maker</b>	MITSUBISHI
<b>Model Number</b>	WS510A
<b>Year</b>	2006
<b>Hour (h)</b>	1643
<b>Serial Number</b>	9W001339

### Upper Structure

<b>Lift Arm Cylinder (Left)</b>	No oil leak
<b>Lift Arm Cylinder (Right)</b>	No oil leak
<b>Bucket Cylinder (Left)</b>	No oil leak
<b>Bucket Cylinder (Right)</b>	No oil leak

### Undercarriage

<b>Front Accel</b>	No oil leak
<b>Rear Accel</b>	No oil leak

### Engine

<b>Model</b>	S4K-E4T
<b>Serial Number</b>	-
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Documents

<b>Automobile Inspection Certificate</b>	No
--	----

### Note for External Appearance

No canopy



### Note for Upper Structure



### Note for Operating Component

- The seat is partly torn and has no backrest
- The handle does not have a horn
- No right mirror



### Note for Undercarriage

- Tire size: 17.5/65-20 10PR
- The tires are worn



### Note for Engine

The radiator fan is partly worn



Lot No ARA013-0057

Admin. No. 2018030501

\*This report is only for your reference. We are not responsible for the actual condition of checked item.