



Inspection Report

Inspection Date: 2023/03/02

Truck

General Information

Maker	ISUZU
Model Number	FRR35C3S
Year	
Mileage (km)	55332
Serial Number	ERR35C3S-7003070

Note for External Appearance

- The outside panels of the carrier are rusty
- The front bumper is bent

Engine

Model	6HL1
Serial Number	
Engine Oil Leak	No
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	Unchecked
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

- F6

Admin. No. 3000046697

*This report is only for your reference. We are not responsible for the actual condition of checked item.