



Inspection Report

Inspection Date: 2023/12/01

Wheel Loader

General Information

Maker	KOMATSU
Model Number	WA30-5E
Year	2003
Hour (h)	3596
Serial Number	WA305E-24193

Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Engine

Model	3D84E-3DB
Serial Number	43527
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Documents

Automobile Inspection Certificate	No
--	----

Note for External Appearance

- The right tail blinker lights and cover are broken
- The right front blinker lights are broken
- The right mirror stay is bent



Note for Upper Structure



Note for Operating Component

- The accel pedal is stiff



Note for Undercarriage



Note for Engine

- Oil oozing from the engine head



Admin. No. 3000053517

*This report is only for your reference. We are not responsible for the actual condition of checked item.