Inspection Report

Inspection Date: 2026/10/29

Excavators

General Information

Maker	KUBOTA		
Model Number	RX-153S		
Year	2015		
Hour (h)	2016	**Meter**	Working
Serial Number	51198		

Options

- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	**Left**	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)		350		

Note for External Appearance

- The bucket side cutters are missing
- Repainted
- The body has rust and scratches



Note for Upper Structure



Undercarriage

	Left	Right
Shoe Type	Rubber	
Swing Circle	No oil leak	
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage

- Adjustable shoe specification
- The left shoe does not retract



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000091174

*This report is only for your reference. We are not responsible for the actual condition of checked item.