



Inspection Report

Inspection Date: 2018/12/08

Excavators


General Information			
Maker	CAT		
Model Number	320D-E		
Year	2013		
Hour (h)	5404	Meter	Working
Serial Number	BWZ08216		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		1030		

Note for External Appearance


- The front parts of the track frame are partly deformed
- The bottom of the body has some dents
- The tool box has some dents and is deformed



Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	NG	OK	
Shoe Link	OK	OK	


Note for Upper Structure

The bottom of the bucket is partly worn, deformed, and has some holes



Note for Undercarriage


- Oil oozing from 2 of the right lower rollers
- 4 of the steps are partly deformed
- 2 of the right shoe plates are chipped



Engine	
Model	JDR-C6.4
Serial Number	GDC72718
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

Rear-view monitor



Note for Engine



Admin No. 2018110303