



# Inspection Report

Inspection Date:

## Forklift

### General Information

<b>Maker</b>	MOROOKA
<b>Model Number</b>	MFD-20
<b>Year</b>	2017
<b>Hour (h)</b>	2311
<b>Serial Number</b>	93114

### Note for External Appearance

- Repainted
- The body has some rust and corrosion

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	NG
<b>Radiator</b>	Not enough cooling water
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

### Note for Engine

- Oil oozing from the hydraulic pump

### Other Information

Admin. No. 3000083849

\*This report is only for your reference. We are not responsible for the actual condition of checked item.