



Inspection Report

Inspection Date: 2026/10/02

Roller

General Information

Maker	HITACHI
Model Number	CC135C-3A
Year	0
Hour (h)	3233
Serial Number	HCM8UL00C00032200

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for External Appearance

- The cover is rusty and has scratches



Note for Undercarriage



Note for Operating Component



Note for Engine



Admin. No. 3000090218

*This report is only for your reference. We are not responsible for the actual condition of checked item.