



# Inspection Report

Inspection Date: 2019/11/05

## Silent Piler

### General Information

<b>Maker</b>	KENCHO
<b>Model Number</b>	PAL SONIC-30
<b>Year</b>	1993
<b>Hour (h)</b>	3355
<b>Serial Number</b>	PS3-024M

### Engine

<b>Model</b>	mitsubishi S6B-PTA
<b>Serial Number</b>	S6B-27974
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Unchecked
<b>Blow-by</b>	Unchecked
<b>Engine Sound</b>	Unchecked
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for External Appearance

### Note for Control Panel

### Note for Engine

Unable to check the condition because the battery is flat; there is no problem according to the seller

### Other Information

- Unable to check the condition because the attachment was not set; there is no problem according to the seller
- The radiator cover is partly rusty and decayed

Admin. No. 2019101250

\*This report is only for your reference. We are not responsible for the actual condition of checked item.