



Inspection Report

Inspection Date: 2026/10/08

Excavators

General Information

Maker	KUBOTA		
Model Number	RX-406		
Year	2014		
Hour (h)	2080	Meter	Working
Serial Number	12221		

Options

- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		Oil oozing	No	Small
Bucket		Oil oozing	No	Small
Bucket Size (mm)		540		

Note for External Appearance

- The overall body has some scratches and rust
- The muffler is damaged



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	NG	NG
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- Oil oozing from the control valve



Note for Undercarriage

- The rubber pads are deteriorated



Engine

Model	D1703
Serial Number	7EZ0084
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000090227

*This report is only for your reference. We are not responsible for the actual condition of checked item.