



Inspection Report


Inspection Date: 2018/03/15

Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-503S		
Year	2004		
Hour (h)	6440	Meter	Working
Serial Number	30118		


Options	
- CAB	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		630		


Note for External Appearance
The serial plate is partly chipped


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
- There is high pitch motor noise while rotating
- Some rubber pads are lost


Engine	
Model	V2203KA
Serial Number	V2203-04W1346
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	Oil oozing

Note for Operating Component
Heater


Note for Engine


Lot No ARA013-0035 Admin No. 2018030701