



Inspection Report


Inspection Date: 2018/12/12

Excavators


General Information			
Maker	YANMAR		
Model Number	B3-6		
Year	2009		
Hour (h)	3470	Meter	Working
Serial Number	60568B		


Options	
- CNP	
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		410		


Note for External Appearance


Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	Oil oozing		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
<ul style="list-style-type: none"> - The rubber pads are partly worn - One of the left shoe links is partly damaged 

Engine	
Model	
Serial Number	41452
Engine Oil Leak	No oil leak
Engine Oil Gauge	Rust/Oil
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	Water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2018120038