



Inspection Report


Inspection Date: 2022/11/24

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK75SR-3		
Year	2012		
Hour (h)	3920	Meter	Working
Serial Number	YT07-25144		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Pippings
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		680		


Note for External Appearance



Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
- Unable to travel straight; it tends to go right.


Engine	
Model	AU-4LE2XYSK-01
Serial Number	4LE2-286500
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
- The seat is partly torn


Note for Engine


Admin No. 3000044374