



Inspection Report

Inspection Date: 2024/11/30

Excavators

General Information

Maker	KOMATSU		
Model Number	PC40MR-3		
Year	2010		
Hour (h)		Meter	Working
Serial Number	18181		

Options

- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	500			

Note for External Appearance

- The body has some rust and scratches
- Repainted



Undercarriage


Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	350	350	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage

- The rubber shoes are loose and deteriorated



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak


Note for Operating Component

- Hour meter is unknown



Note for Engine

- The battery is flat; the engine started with the booster cables



Admin No. 3000067033