



Inspection Report

Inspection Date: 2024/12/14

Excavators

General Information

Maker	KOMATSU		
Model Number	PC128US-10		
Year	2016		
Hour (h)	4540	Meter	Working
Serial Number	45967		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	Yes	Small
Bucket Size (mm)	830			

Note for External Appearance

- Partially repainted



Undercarriage


Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	NG	NG	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage

- Oil oozing from some lower rollers (1 on the left and 3 on the right)
 - The rubber pads are deteriorated; some rubber pad are missing



Engine

Model	SAA4D95LE-6
Serial Number	716046
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000067038