



# Inspection Report

Inspection Date:

## Aerial Work Platform

### General Information

<b>Maker</b>	JLG
<b>Model Number</b>	2030ES
<b>Year</b>	2008
<b>Hour (h)</b>	293
<b>Serial Number</b>	0200182369

### Note for External Appearance

- Repainted
- The body is rusty and has some scratches

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	#N/A
<b>Engine Oil Gauge</b>	#N/A
<b>Exhaust Color</b>	#N/A
<b>Blow-by</b>	#N/A
<b>Engine Sound</b>	#N/A
<b>Radiator</b>	#N/A
<b>Water Pump</b>	#N/A
<b>Injection Pump</b>	#N/A

### Note for Control Panel

### Note for Engine

### Other Information

- Not moving

Admin. No. 3000066671

\*This report is only for your reference. We are not responsible for the actual condition of checked item.