



Inspection Report

Inspection Date: 2020/07/04

Excavators

General Information

Maker	HITACHI		
Model Number	ZX200-3		
Year	2013		
Hour (h)	5940	Meter	Working
Serial Number	HCM1U100K00223223		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Arm Crane | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	1030			

Note for External Appearance

- The body is rusty and damaged
- Rear-view camera



Note for Upper Structure



Undercarriage

Shoe Type	Steel	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	790	790
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage



Engine

Model	4HK1
Serial Number	70429
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000011663