



Inspection Report


Inspection Date: 2017/09/13

Excavators


General Information			
Maker	KOBELCO		
Model Number	U-30-3S		
Year	2006		
Hour (h)	2516	Meter	Working
Serial Number	61235		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		430		


Note for External Appearance
Not original color


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No confirmation of movement		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
The left rubber shoe has deteriorated over time and are worn


Engine	
Model	D1503
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2017090023