



Inspection Report

Inspection Date: 2024/12/05

Excavators

General Information

Maker	KOMATSU		
Model Number	PC138US-11		
Year	2019		
Hour (h)	6154	Meter	Working
Serial Number	55440		

Options

- CAB	- Speed changer
	- Air conditioner

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	840			

Note for External Appearance

- Repainted



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- The arm has been reinforced



Note for Undercarriage

- The rubber pads are deteriorated




Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component

- The seat is dirty
- Errors display on the monitor



Note for Engine



Admin No. 3000064083