



Inspection Report

Inspection Date: 2018/10/04

Generator

General Information

Maker	DENYO
Model Number	DCA-220ESM
Year	-
Hour (h)	10290
Serial Number	3717487

Note for External Appearance

Engine

Model	6D24-TLE2B
Serial Number	6D24-331408
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Oil leak from the upper part of the engine oil pan

Admin. No. 2018100012

*This report is only for your reference. We are not responsible for the actual condition of checked item.