



Inspection Report


Inspection Date: 2018/12/06

Excavators


General Information			
Maker	KUBOTA		
Model Number	U-30-5		
Year			
Hour (h)	1265	Meter	Working
Serial Number	79434		

Options	
- CNP	
- Blade	- Breaker Pipings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	N/A	
Arm		No	No	Small
Bucket		No	No	Unchecked
Bucket Size (mm)		430		


Note for External Appearance



Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	NG	OK
Shoe Link	OK	OK

Note for Upper Structure
<ul style="list-style-type: none"> - Oil oozing from the swing cylinder - A standard bucket will be attached before shipment - The attachment in the picture is not for sale - 2 sides of the arm have been reinforced


Note for Undercarriage
Rusty


Engine	
Model	
Serial Number	7EZ0936
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component


Note for Engine
The battery is broken (it works with booster cables)


Admin No. 2018110340