



Inspection Report

Inspection Date: 2018/07/10

Finisher

General Information

Maker	SUMITOMO
Model Number	HA14S
Year	
Hour (h)	3006
Serial Number	200

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Radiator	Unchecked
Water Pump	No water leak
Injection Pump	No fuel leak

Note for External Appearance

Note for Control Panel

Note for Engine

Engine movement is unchecked because one of the hydraulic hoses is broken according to the seller

Other Information

Traveling motion is unchecked (this item was inspected without starting the engine)

Admin. No. 2018070055

*This report is only for your reference. We are not responsible for the actual condition of checked item.