



Inspection Report


Inspection Date: 2017/10/05

Excavators


General Information			
Maker	HANIX		
Model Number	N260-2		
Year			
Hour (h)	2192	Meter	Not Working
Serial Number	N2610878		


Options	
- CNP	- Speed changer
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Unchecked
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)		410		


Note for External Appearance
The VIN is unchecked



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The movement of the upper structure is unchecked


Note for Undercarriage
- Traveling motion is unchecked
- The rubber shoes have deteriorated over time


Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	-

Note for Operating Component
- The seat is partly torn
- The roof is partly cracked


Note for Engine
- The battery is flat
- The movement of the engine is unchecked


Lot No ARA010-0025 Admin No. 2017100030