



Inspection Report

Inspection Date:

Aerial Work Platform

General Information

Maker	AICHI
Model Number	SR21A
Year	2004
Hour (h)	7181
Serial Number	684850

Engine

Model	4JG1
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for External Appearance

- Repainted
- The body is rusty and has some scratches
- The frame of the upper control boarding cage is deformed

Note for Control Panel

Note for Engine

Other Information

Admin. No. 3000060812

*This report is only for your reference. We are not responsible for the actual condition of checked item.