Inspection Report

Inspection Date: 2025/07/15

Wheel Loader

General Information	
Maker	YANMAR
Model Number	V3-6
Year	2013
Hour (h)	3591
Serial Number	V36-62013

Upper Structure	
Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage	
Front Accel	No oil leak
Rear Accel	No oil leak

Engine	
Model	3TNV88-BNKAH
Serial Number	K5731
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Documents	
Automobile Inspection Certificate	No

Note for External Appearance

- CAB
- EPA

Note for Upper Structure

Note for Operating Component

- The seat is torn
- With heater

Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.

Note for Engine

Admin. No. 3000074110

*This report is only for your reference. We are not responsible for the actual condition of checked item.