



Inspection Report

Inspection Date: 2018/09/15

Roller

General Information

| | |
|---------------|---------|
| Maker | SAKAI |
| Model Number | TW350-1 |
| Year | |
| Hour (h) | 2262 |
| Serial Number | 10449 |

Engine

| | |
|------------------|---------------|
| Model | 3LD1 PA-29 |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Water Pump | No water leak |
| Radiator | OK |

Note for External Appearance



Note for Undercarriage

The roller occasionally does not have enough power according to the seller



Note for Operating Component

The seat is partly torn



Note for Engine



Admin. No. 2018090181

*This report is only for your reference. We are not responsible for the actual condition of checked item.