



Inspection Report

Inspection Date: 2019/06/17

Excavators

General Information

Maker	KOBELCO		
Model Number	SK40SR-5		
Year	2007		
Hour (h)	5456	Meter	Working
Serial Number	PH07-06103		

Options

- CNP	- Speed changer
- Multilever	
- Blade	- Pippings
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Small
Bucket Size (mm)		540		

Note for External Appearance

- The body is partly repainted with a brush
- The cover under the seat has some dents and is partly decayed
- The covers are partly damaged and rusty



Note for Upper Structure

The blade has some dents



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage

- The rubber shoes have deteriorated over time and are worn
- The track frames are rusty



Engine

Model	4TNV88-BXYB
Serial Number	82827
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

The seat is partly torn



Note for Engine

- Oil oozing from the control valve
- Oil oozing from around the oil pan



Admin No. 2019060650