



Inspection Report

Inspection Date: 2024/11/15

Excavators

General Information

Maker	KOMATSU		
Model Number	PC45MR-5		
Year	2017		
Hour (h)	5002	Meter	Working
Serial Number	KMTPC259THE030957		

Options


- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	Yes	Small
Bucket Size (mm)	500			

Note for External Appearance

- The covers have some rust, scratches, and dents
 - Oil oozing from the bottom cover



Undercarriage


Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage

- The right upper roller is distorted and worn
 - The rubber shoes have some cracks



Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for Operating Component



Note for Engine



Admin No. 300066231