



Inspection Report

Inspection Date:

Asphalt Finisher

General Information

Maker	SUMITOMO
Model Number	HA45W-7
Year	2010
Hour (h)	6382
Serial Number	HANF45W3V00050523

Note for External Appearance

- The cover is rusty and partly damaged
- Oil oozing from the screed lift cylinder
- Oil oozing from the level cylinder
- Oil oozing from the hopper cylinder
- The seat is torn

Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

- Oil oozing from the main pump
- Engine blow by

Other Information

Admin. No. 3000041083

*This report is only for your reference. We are not responsible for the actual condition of checked item.