



Inspection Report

Inspection Date: 2018/12/05


Excavators

General Information			
Maker	YANMAR		
Model Number	ViO20-2		
Year	2000		
Hour (h)	2425	Meter	Working
Serial Number	20788B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		420		

Note for External Appearance
The body is not the original color




Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	NG	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The boom has some plays
- Quick hitch




Note for Undercarriage
The bearing of one of the left lower rollers is broken




Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Black/Gray
Exhaust Color	Black/Gray
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn



Note for Engine



Admin No. 2018110725