



# Inspection Report

Inspection Date: 2022/08/23


## Excavators

General Information			
Maker	YANMAR		
Model Number	B3-6A		
Year	2011		
Hour (h)	3650	Meter	Working
Serial Number	62856B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		425		

Note for External Appearance
- The crane hook has been detached




Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The bolts of the bucket side cutters are missing




Note for Undercarriage
- The crane monitor is unclear and can't read the numbers



Engine	
Model	3TNV82A-NBV2
Serial Number	89260
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
------------------------------



Note for Engine
-----------------



Admin No. 3000049974