



Inspection Report

Inspection Date: 2018/10/04

Generator

General Information

Maker	DENYO
Model Number	DCA-90ESH
Year	
Hour (h)	
Serial Number	3796391

Note for External Appearance

Engine

Model	J08C-P
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

The hour meter has been replaced (1382h+8710h)

Note for Engine

Admin. No. 2018100016

*This report is only for your reference. We are not responsible for the actual condition of checked item.