



# Inspection Report


Inspection Date: 2018/03/13

## Excavators


| General Information |            |       |         |
|---------------------|------------|-------|---------|
| Maker               | KOBELCO    |       |         |
| Model Number        | SK30SR     |       |         |
| Year                | 2003       |       |         |
| Hour (h)            | 3248       | Meter | Working |
| Serial Number       | PW10-22593 |       |         |


| Options      |  |
|--------------|--|
| - CNP        |  |
| - Multilever |  |
| - Blade      |  |
| - EPA        |  |
| - Pipings    |  |

| Upper Structure |                  |          |              |       |
|-----------------|------------------|----------|--------------|-------|
|                 |                  | Cylinder |              | Play  |
|                 |                  | Oil Leak | Scratch/Rust |       |
| Boom            | Left             | No       | No           | Small |
|                 | Right            | N/A      | N/A          |       |
|                 | Arm              | No       | No           | Small |
|                 | Bucket           | No       | No           | Big   |
|                 | Bucket Size (mm) | 450      |              |       |


| Note for External Appearance  |
|---|
|  |


| Undercarriage   |                              |       |
|-----------------|------------------------------|-------|
| Shoe Type       | Steel shoes with rubber pads |       |
| Swing Circle    | No oil leak                  |       |
|                 | Left                         | Right |
| Shoe Width (mm) | 300                          | 300   |
| Idler           | NG                           | NG    |
| Sprocket        | OK                           | OK    |
| Pin Bush        | OK                           | OK    |
| Upper Roller    | OK                           | OK    |
| Track Roller    | OK                           | OK    |
| Shoe Link       | NG                           | NG    |

| Note for Upper Structure  |
|---|
| No working lamp   |
|  |

| Note for Undercarriage   |
|--|
| - Unable to travel straight (the left shoe speed is slow; unable to make left pivot turns) |
| - The rubber pads are worn   |
| - The shoe links are slightly worn   |
|       |

| Engine           |               |
|------------------|---------------|
| Model            | 3TNE82A-EYBC  |
| Serial Number    | -             |
| Engine Oil Leak  | Oil leak      |
| Engine Oil Gauge | OK            |
| Radiator         | OK            |
| Exhaust Color    | Normal        |
| Blow-by          | No            |
| Engine Sound     | OK            |
| Hydraulic Pump   | No oil leak   |
| Water Pump       | No water leak |
| Oil Cooler       | No oil leak   |
| Motor            | Unchecked     |
| Multi Lever      | No oil leak   |

| Note for Operating Component  |
|---|
| One of the switches is lost   |
|  |

| Note for Engine   |
|---|
| Oil leak from the hydraulic hose  |
|  |

Lot No ARA013-0040 Admin No. 2018030502