



Inspection Report

Inspection Date: 2023/01/14

Generator

General Information

Maker	DENYO
Model Number	DCA-150ESM
Year	
Hour (h)	12632
Serial Number	3828259

Note for External Appearance

- Concrete adheres to the covers

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	Unchecked
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- The hour meter has been replaced (actual hour =1435+11197h)

Note for Engine

Admin. No. 3000045255

*This report is only for your reference. We are not responsible for the actual condition of checked item.