



Inspection Report

Inspection Date: 2022/09/17

Excavators

General Information

Maker	KOMATSU		
Model Number	PC200-8N1		
Year	2008		
Hour (h)	4116	Meter	Working
Serial Number	KMTPC197C02313910		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	Yes	Big
Bucket Size (mm)		1030		

Note for External Appearance

- The covers are damaged and have some dents
- The left mirror is cracked



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	700	700
Idler	OK	OK
Sprocket	OK	NG
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	NG	OK
Shoe Link	OK	OK

Note for Upper Structure

- The boom has some cracks
- The bucket has some dents and cracks
- The tip of the arm has some dents



Note for Undercarriage

- The speed changer is broken
- Oil oozing from 3 left lower rollers and 3 right lower rollers



Engine

Model	SAA6D107E-1
Serial Number	26527982
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The air conditioner is broken (no cold air)
- The crane device is broken (the displaying numbers don't respond)



Note for Engine



Admin No. 3000042429