



Inspection Report

Inspection Date: 2017/09/12

Excavators

General Information

Maker	KUBOTA		
Model Number	U-40-3S		
Year	2007		
Hour (h)	-	Meter	Replaced
Serial Number	31472		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | - Pipings |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
	Arm	No	No	Big
	Bucket	No	No	Big
	Bucket Size (mm)	550		

Note for External Appearance

- Not original color
- No caution plate



Undercarriage

Shoe Type	Rubber	
Swing Circle	No confirmation of movement	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

The covers of the travel motors are deformed



Engine

Model	V2203
Serial Number	07A5768
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component

The hour meter has been replaced (2920h+44h)



Note for Engine



Admin No. 2017090719